Qty:

Each

1 Um:

: HEAD REST ASSEMBLY CENTER

: D412724041

: 30/09/2008

: N/A

: N/A

: N/A

Thursday, 18/09/2008 8:53:30 AM

User: Julie Lecocq

## **Process Sheet**

**Drawing Name** 

Part Number

Material

**Due Date** 

**Drawing Number** 

Project Number

**Drawing Revision** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 42084

**Estimate Number** 

: 10861

P.O. Number

Prsht Rev.

First Issue

This Issue

: 18/09/2008

: NC

: //

: 42083

**Previous Run** Written By

Checked & Approved By

Comment

: Est Rev:A 04.09.08

Type

S.O. No. :

New Issue KJ/JLM

: SMALL /MED FAB

**Additional Product** 



Seq. #:

**Machine Or Operation:** 

Description: DOCUMENT CONTROL

DC 1.0

Comment: DOCUMENT CONTROL

If D412-724-041 is a W/O on it's own,

Photocopy bluefile and create labels per PPP D412-724-041 CHG001

2.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

3.0 D3303041 Head Rest



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Pick: Packing Kit **Qty Part Number** 

D3303-041

Description **Head Rest** 

Batch

D3304041 4.0



1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Comment: Qty.: Pick: Packing Kit

**Qty Part Number** 

Description

Batch

D3304-041 **Tube Assembly**  40860

AN52510R6 5.0



Comment: Qty.:

4.0000 Each(s)/Unit Total:

4.0000 Each(s)

Screw

Pick: Packing Kit

**Qty Part Number** 

Description Batch 1101203

08/09/24M

Page 1

Dart Aerospace L	Lla
------------------	-----

W/O:	•		WC	ORK ORDER CHANG	ES				<del></del>			
DATE	STEP	PROCEDURE CHANGE			Ву	C	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No:		PAR #:	Fault Cate	Fault Category:NC			NCR: Yes No DQA: Date:					
Resolution:			Dispositio	Disposition: Q			ed:	Date:	Date:			
NCR:		. \	WORK ORD	ER NON-CONFORM	ANCE (N	CR)						
DATE	STEP	Section A	Corrective Action Section B				Verification		Approval			
			Initial A Chief Eng	Action Description Chief Eng		n & ate	Section C	Chief Eng	QC Inspector			
		•										
			;									

NOTE: Date & initial all entries

Date: Thursday, 18/09/2008 8:53:30 AM Julie Lecocq User: **Process Sheet** Drawing Name: HEAD REST ASSEMBLY CENTER Customer: CU-DAR001 Dart Helicopters Services Part Number: D412724041 Job Number: 42084 Job Number: Description: Seq. #: **Machine Or Operation:** Screw AN525-10R6 INSPECT 100% KITS FOR COMPLETENESS 6.0 QC4 081 Comment: INSPECT 100% KITS FOR COMPLETENESS 7.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-724-041 Location: 08/09/249 PPP Rev: FINAL INSPECTION/W/O RELEASE 8.0 QC21



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



h 68 mg 24

W/O:	rospace Lt		W	ORK ORDER CHANGES	3					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								Ē		
Part No: PAR #:		Fault Cat	Fault Category: N			NCR: Yes No DQA: Date:				
	Reso	lution:	Dispositi	on:	QA: N/C C	losed:		Date: _		
NCR:			WORK ORE	DER NON-CONFORMAN	ICE (NCI	R)				
		Description of NC	Corrective Action Section B		В	Verif	ication	Approval Chief Eng	Approval QC Inspecto	
DATE	STEP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	Section C				
								1		
					Į					

NOTE: Date & initial all entries